

Monitoring Data Record

Project Title: R-2547C (Site 8B) COE Action ID: 2002-2-0819  
 Stream Name: UT to Marks Creek DWQ Numbers: 011689  
 City, County and other Location Information: Wake County, Knightdale Bypass  
(Sta.134+40 to 137+00 -L-)  
 Date Construction Completed: November 2004 Monitoring Quarter: ( 7 ) of 8  
 Ecoregion: \_\_\_\_\_ 8 digit HUC unit: 03020201  
 USGS Quad Name and Coordinates: \_\_\_\_\_

**Rosgen Classification:** \_\_\_\_\_

Length of Project: 249' Urban or Rural: Rural Watershed Size: \_\_\_\_\_

Monitoring DATA collected by: J. Young Date: 11/21/07

## Applicant Information:

Name: NCDOT Roadside Environmental Unit

Address: 1425 Rock Quarry Rd. Raleigh, NC 27610

Telephone Number: (919) 861-3772 Email address: mlgreen@dot.state.nc.us

## Consultant Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Telephone Number: \_\_\_\_\_ Email address: \_\_\_\_\_

**Project Status:** Complete

**Monitoring Level required by COE and DWQ (404 permit/ 401 Cert.):** Level 1 2 3

Monitoring Level 1 requires completion of *Section 1, Section 2 and Section 3*

**Permit States:** The permittee will visually monitor the vegetative plantings on all mitigation streambanks to access and insure complete stabilization of the mitigation stream segments. This monitoring will include adequate visual monitoring of planted vegetation for a minimum of two years after final planting, and appropriate remedial actions (e.g., replanting, streambank grading, ect.). If within any monitoring year, bank stabilization is not acceptable as determined by the Corps of Engineers, and remedial action required by the Corps of Engineers is performed, the two year monitoring of the affected portions of the stream will begin again.

Section 1. PHOTO REFERENCE SITES

**Total number of reference photo locations at this site:**

**3 photo point locations - 2 photos at each location**

**Dates reference photos have been taken at this site:** 4/18/06, 8/4/06, 11/15/06, 3/14/07, 5/31/07, 8/9/07, 11/21/07

**Individual from whom additional photos can be obtained (name, address, phone):** \_\_\_\_\_

Other Information relative to site photo reference: \_\_\_\_\_

If required to complete Level 3 monitoring only stop here; otherwise,

**Section 2. PLANT SURVIVAL**

**Attach plan sheet indicating reference photos.**

Identify specific problem areas (missing, stressed, damaged or dead plantings):

---

---

---

Estimated causes, and proposed/required remedial action:

---

---

---

ADDITIONAL COMMENTS: Live stakes and bareroot seedlings noted on the streambank and in the floodplain consisted of black willow, baldcypress, green ash, swamp chestnut oak, overcup oak, sweetgum, sycamore, and tulip poplar. Other vegetation noted consisted of *Juncus* sp., cattail, briars, lespedeza, fennel, woolgrass, and various grasses.

If required to complete Level 1 and Level 2 monitoring only stop here; otherwise, complete section 3.

### Section 3. CHANNEL STABILITY

**Visual Inspection:** The entire stream project as well as each in-stream structure and bank stabilization/revetment structure must be evaluated and problems addressed.

Report on the visual inspection of channel stability. Physical measurements of channel stability/morphology will not be required. Include a discussion of any deviations from as-built and an evaluation of the significance of these deviations and whether they are indicative of a stabilizing or destabilizing situation.

The stream is stable for the 7th quarter of monitoring. There was no water flowing in the stream at the time of monitoring. NCDOT will continue to monitor this stream relocation.

---

---

---

---

---

Date Inspected	Station Number	Station Number	Station Number	Station Number	Station Number
Structure Type					
Is water piping through or around structure?					
Head cut or down cut present?					
Bank or scour erosion present?					
Other problems noted?					

**NOTE:** Attach separate narrative sheets to each monitoring report describing/discussing the overall monitoring results. Include the identification of specific problem areas/channel failures, estimated cause and proposed/required remedial action. This should include a brief discussion of any parameter that has changed significantly from as-built.



# Site 8B



Photo 1 (Upstream)



Photo 2 (Downstream)



Photo 3 (Upstream)



Photo 4 (Downstream)



Photo 5 (Upstream)



Photo 6 (Downstream)

7th Quarter – November 2007